

Bengaluru Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	10
2	Total number of branches where construction of Ramps is not feasible (*)	23
3	Total number of branches where construction of Ramps is feasible (**)	Nil

1. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	032	Vellore	Entrance is at road level
2.	044	Bangalore City	Branch in first floor
3.	076	Gulbarga	Branch in first floor
4.	088	Bangalore Cantonment	Entrance is at a height, with many steps
5.	101	Mangalore	Entrance is at a height, with many steps
6.	137	Hassan	Branch in first floor
7.	145	Hosur	Branch in first floor
8.	188	Ranipet	Branch in first floor
9.	191	Krishnagiri	Entrance is at road level
10.	193	Arakonam	Entrance is at road level
11.	212	Gudiyatham	Branch in first floor
12.	246	Kaveripattinam	Entrance is at road level
13.	251	Arcot	Entrance is at a height, with many steps
14.	260	Nelamangala	Branch in first floor
15.	263	Katpadi	Entrance is at a height, with many steps
16.	277	Hebbagodi	Branch in first floor
17.	336	Kanakapura	Branch in first floor
18.	337	Tirupathur	Entrance is at road level
19.	342	Ambur	Entrance is at road level
20.	416	Yadgiri	No space
21.	428	Channapatna	Branch in first floor
22.	486	Ranebennur	Branch in Upper Ground Floor
23.	487	Bagalkot	Branch in first floor

2. Progress in construction of Ramp at branches, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	The progress in construction of Ramp	Remarks
			Nil	

Bengaluru Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	23
2	Total number of ATMs where construction of Ramps is not feasible (*)	42
3	Total number of ATMs where construction of Ramps is feasible (**)	Nil

2. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl. No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
1	032	Vellore	TMB03201	Entrance is at road level
2	032	Vellore	TMB03202	Entrance is at road level
3	032	Vellore	TMB03203	Entrance is at road level
4	044	Bangalore City	TMB04401	ATM is in first floor
5	044	Bangalore City	TMB04402	Entrance is at a height, with many steps
6	076	Gulbarga	TMB07602	ATM is at road level
7	076	Gulbarga	TMB07603	ATM is at road level
8	088	Bangalore Cantonment	TMB08801	Entrance is at a height, with many steps
9	101	Mangalore	TMB10101	Entrance is at a height, with many steps
10	137	Hassan	TMB13701	Entrance is at road level
11	145	Hosur	TMB14502	Entrance is at road level
12	145	Hosur	TMB14503	Entrance is at road level
13	145	Hosur	TMB14504	Entrance is at road level
14	145	Hosur	TMB14505	Entrance is at road level
15	188	Ranipet	TMB18801	Entrance is at road level
16	188	Ranipet	TMB18802	Near to highway
17	191	Krishnagiri	TMB19102	Nearer to road
18	191	Krishnagiri	TMB19103	Entrance is at a height, with many steps
19	212	Gudiyatham	TMB21201	Entrance is at a height, with many steps
20	246	Kaveripattinam	TMB24601	Entrance is at road level
21	251	Arcot	TMB25101	Entrance is at a height, with many steps
22	251	Arcot	TMB25102	Entrance is at road level, Inadequate space
23	259	Anekal	TMB25901	Entrance is at road level
24	260	Nelamangala	TMB26001	ATM is in first floor
25	263	Katpadi	TMB26301	Entrance is at a height, with many steps
26	263	Katpadi	TMB26302	Very nearer to road
27	277	Hebbagodi	TMB27701	Entrance is at road level
28	277	Hebbagodi	TMB27703	Entrance is at road level
29	336	Kanakapura	TMB33601	Entrance is at road level
30	337	Tirupathur	TMB33701	Entrance is at road level
31	342	Ambur	TMB34201	Entrance is at road level
32	044	Bangalore city	TMB04404	Not feasible
33	416	Yadgiri	TMB41601	No space
34	428	Channapatna	TMB42801	Entrance is at road level

35	415	Vengatadampatti	TMB41502	No space
36	032	Vellore	TMB03204	Entrance is at more height from the earth level
37	486	Ranebennur	TMB48601	No space, with five steps
38	415	Vengatadampatti	TMB41501	Not Feasible
39	487	Bagalkot	TMB48701	The platform started next to the entrance of our branch onsite ATM
40	499	Dod ballapur	TMB49901	Entrance is at floor level
41	277	Hebbagodi	TMB27704	Entrance is at a height, with many steps
42	145	Hosur	TMB14507	Entrance is at a height, with many steps

3. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp	Remarks
		Nil			

Chennai Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	22
2	Total number of branches where construction of Ramps is not feasible (*)	33
3	Total number of branches where construction of Ramps is feasible (**)	Nil

2. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	008	Chennai 21	Entrance is at road level
2.	020	Chennai GT	Branch in first floor
3.	055	Chennai T Nagar	Entrance area is common to the apartment
4.	096	Mount Road	Entrance at road level
5.	105	Kancheepuram	Branch in first floor
6.	108	Pondhicherry	Entrance at a height with many steps
7.	157	Perambur	Entrance at road level
8.	158	Thiruvanmiyur	Entrance at height with many steps
9.	160	Chengalpattu	Branch in first floor
10.	161	Anna Nagar	Branch is in first floor
11.	165	Purasawalkam	Branch in first floor
12.	196	Sholinganallur	Branch in first floor
13.	210	Pallavaram	Branch in first floor
14.	216	Melmaruvathur	Branch is in first floor
15.	227	Madipakkam	Branch is in first floor
16.	228	Naravarikuppam	Branch in first floor
17.	234	Chitlapakkam	Branch in first floor
18.	235	Medavakkam	Branch in first floor
19.	282	Adayalampattu	Branch in first floor
20.	323	Port Blair	Branch in first floor
21.	367	Sikkarayapuram	Entrance at road level
22.	370	Ayapakkam	Entrance at road level
23.	388	Neelankarai	Entrance at road level
24.	396	Pallikaranai	Branch in first floor
25.	410	Nerkundram	Entrance at road level
26.	424	Kelambakkam	Branch in first floor
27.	436	Adayar	Branch in first floor
28.	445	Madambakkam	Branch in first floor
29.	450	Chennai_Mylapore	There are more steps
30.	454	Chennai_Velachery	Branch in first floor
31.	465	Nungambakkam	Branch in first floor
32.	481	Kodambakkam	Branch in first floor
33.	346	Senneerkupam	No space

3. Progress in construction of Ramp at branches, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	The progress in construction of Ramp	Remarks
			Nil	

Chennai Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	52
2	Total number of ATMs where construction of Ramps is not	107

	feasible (*)	
3	Total number of ATMs where construction of Ramps is feasible (**)	Nil

2. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
1	105	Kancheepuram	TMB10501	Entrance will be disturbed
2	096	Chennai Mount Road	TMB09601	Entrance is at road level
3	096	Chennai Mount Road	TMB09602	Entrance is at road level
4	096	Chennai Mount Road	TMB09603	Entrance is at road level
5	108	Pondicherry	TMB10801	Entrance is at road level
6	108	Pondicherry	TMB10802	Entrance is at road level
7	108	Pondicherry	TMB10803	Entrance is at road level
8	108	Pondicherry	TMB10804	Entrance is at road level
9	108	Pondicherry	TMB10805	Entrance is at road level
10	108	Pondicherry	TMB 10806	Entrance is at a height with many steps
11	146	Tambaram	TMB14601	Entrance is at road level
12	146	Tambaram	TMB14602	Entrance is at road level
13	146	Tambaram	TMB14603	Entrance is at road level
14	146	Tambaram	TMB14604	Entrance is at road level
15	147	Karaikal	TMB14702	Entrance is at a height with many steps
16	147	Karaikal	TMB14703	Entrance is at road level
17	158	Thiruvanmiyur	TMB15801	Entrance is at a height with many steps
18	158	Thiruvanmiyur	TMB15802	Entrance is at road level
19	158	Thiruvanmiyur	TMB15803	Entrance is at road level
20	160	Chengalpattu	TMB16001	Entrance is at road level
21	165	Purasawalkam	TMB16502	ATM is in road corner. No sufficient space to construct RAMP
22	196	Sholinganallur	TMB19601	Entrance is at road level
23	196	Sholinganallur	TMB19602	Entrance is at road level
24	204	Poonamallee	TMB20402	Entrance is at road level
25	204	Poonamallee	TMB20403	Entrance is at a height, with many steps
26	204	Poonamallee	TMB20404	Entrance is at road level
27	208	Maduravoyal	TMB20802	Entrance is at a height, with many steps
28	208	Maduravoyal	TMB20803	Entrance is at a height, with many steps
29	208	Maduravoyal	TMB20804	Entrance is at a height, with many steps
30	208	Maduravoyal	TMB20805	Entrance is at a height, with many steps

31	208	Maduravoyal	TMB20806	Entrance is at a height, with many steps
32	208	Maduravoyal	TMB20807	Entrance is at a height, with many steps
33	210	Pallavaram	TMB21001	Entrance is at road level
34	210	Pallavaram	TMB21003	Entrance is at road level
35	216	Melmaruvathur	TMB21601	Entrance is at road level
36	216	Melmaruvathur	TMB21602	Entrance is at road level
37	228	Naravarikuppam	TMB22803	Entrance is at road level
38	228	Naravarikuppam	TMB22802	Entrance is at road level
39	228	Naravarikuppam	TMB22804	Entrance is at road level
40	229	Porur	TMB22903	Entrance is at road level
41	229	Porur	TMB22904	Entrance is at a height, with many steps
42	234	Chitlapakkam	TMB23401	Entrance is at road level
43	234	Chitlapakkam	TMB23402	Entrance is at a height, with many steps
44	280	Chekkadu	TMB28001	Entrance is at road level
45	282	Adayalampattu	TMB28201	Entrance is at road level
46	282	Adayalampattu	TMB28202	Entrance is at road level
47	367	Sikkarayapuram	TMB36701	Entrance is at road level
48	388	Neelankarai	TMB38801	Entrance is at road level
49	396	Pallikaranai	TMB39601	Entrance is at road level
50	399	Ponneri	TMB39901	Entrance is at road level
51	209	Thiruvallur	TMB20901	Entrance is at road level
52	020	Chennai Gt	TMB02003	Entrance is at road level
53	020	Chennai Gt	TMB02004	Entrance is at a height, with many steps
54	235	Medavakkam	TMB23501	Entrance is at road level
55	235	Medavakkam	TMB23502	Entrance is at road level
56	235	Medavakkam	TMB23503	Entrance is at road level
57	227	Madipakkam	TMB22701	Entrance is at road level
58	227	Madipakkam	TMB22702	Entrance is at road level
59	227	Madipakkam	TMB22703	Entrance is at a height, with many steps
60	055	Tnagar	TMB05505	Entrance area is common area to the Apartment
61	055	Tnagar	TMB05504	Entrance is at road level
62	055	Tnagar	TMB05503	Entrance is at road level
63	008	Chennai 21	TMB00801	Entrance is at road level
64	008	Chennai 21	TMB00802	Entrance is at road level
65	008	Chennai 21	TMB00803	Entrance is at road level
66	008	Chennai 21	TMB00804	Entrance is at road level
67	008	Chennai 21	TMB00805	Entrance is at road level
68	008	Chennai 21	TMB00806	Entrance is at road level
69	008	Chennai 21	TMB00807	Entrance is at road level
70	008	Chennai 21	TMB00808	Entrance is at road level

71	008	Chennai 21	TMB00809	Entrance is at road level
72	008	Chennai 21	TMB00810	Entrance is at road level
73	157	Perambur	TMB15701	Entrance is at road level
74	157	Perambur	TMB15702	Entrance is at road level
75	215	Guduvancheri	TMB21501	Entrance is at road level
76	142	Aminjikarai	TMB14201	Entrance is at road level
77	205	Valasaravakkam	TMB20502	Entrance is at road level
78	205	Valasaravakkam	TMB20503	Entrance is at road level
79	205	Valasaravakkam	TMB20504	Entrance is at road level
80	205	Valasaravakkam	TMB20505	Entrance is at road level
81	280	Chekkadu	TMB28002	Entrance is at road level
82	280	Chekkadu	TMB28003	Entrance is at road level
83	280	Chekkadu	TMB28004	Entrance is at road level
84	280	Chekkadu	TMB28005	Entrance is at road level
85	161	Chennai Anna nagar	TMB16104	Entrance is at road level
86	161	Chennai Anna nagar	TMB16105	Entrance is at road level
87	161	Chennai Anna nagar	TMB16106	Entrance is at road level
88	161	Chennai Anna nagar	TMB16107	Entrance is at road level
89	008	Chennai-21	TMB00811	Entrance is at a height, with many steps
90	208	Maduravoyal	TMB20807	No space
91	396	Pallikaranai	TMB39601	Entrance is at road level
92	410	Nerkundram	TMB41001	Entrance is at road level
93	229	Porur	TMB22905	Entrance is at road level
94	436	Adayar	TMB43601	Entrance at ground level
95	147	Karaikal	TMB14704	Entrance at ground level
96	370	Ayapakkam	TMB37002	Entrance is at Height with many steps (6 steps)
97	454	Chennai_Velachery	TMB45401	Entrance is at more height from the earth level
98	228	Naravarikuppam	TMB22801	Entrance at Road level
99	202	sriperumbudur	TMB20201	In front of door there is pipeline connection and earth hole is there
100	229	Porur	TMB22906	Entrance is at in front of road
101	161	Chennai Anna nagar	TMB16102	Not feasible
102	161	Chennai Anna nagar	TMB16103	Not feasible
103	020	Chennai GT	TMB02001	Entrance is only 1/2 feet height from floor.
104	020	Chennai Gt	TMB02002	No space busy area
105	055	T Nagar	TMB05502	Entrance is at Height with many steps (8 steps)
106	215	Guduvancheri	TMB21503	Entrance is at road level(One step available)
107	008	Chennai – 21	TMB00813	Entrance is at road level

3. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp
Nil				

Coimbatore Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	31

2	Total number of branches where construction of Ramps is not feasible (*)	18
3	Total number of branches where construction of Ramps is feasible (**)	Nil

1. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	016	Coimbatore Main	Branch is in complex
2.	075	Tirupur	Entrance at low level
3.	090	Pollachi	Entrance at a height
4.	121	Dr.Nanjappa Road	Entrance is at a height
5.	136	Coimbatore R.S.Puram	Entrance at a height with many steps
6.	179	Perundurai	Entrance is at a height with many steps
7.	203	Kunnathur	Branch is at first floor
8.	224	Neelambur	Entrance is at road level
9.	232	Kavundampalayam	Branch is at first floor
10.	245	Avinashi	Entrance is at road level
11.	305	Coonoor	Branch is at first floor
12.	325	Pallagoundenpalayam	Entrance is at road level
13.	364	Somayampalayam	Entrance is at road level
14.	374	Malayandipatnam	Due to drainage
15.	376	Saravanampatti	Entrance is at a height with many steps
16.	397	Gudalur	Entrance is at road level
17.	420	Coimbatore Singanallur	Entrance is at a height with many steps
18.	140	Mettupalayam	Entrance is at road level

2. Progress in construction of Ramp at branches, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	The progress in construction of Ramp	Remarks
			Nil	

Coimbatore Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	68
2	Total number of ATMs where construction of Ramps is not feasible (*)	50

3	Total number of ATMs where construction of Ramps is feasible (**)	Nil
---	---	-----

2. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl. No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
1	201	Sathyamangalam	TMB20101	Spiral Staircase for the first floor is situated near the ATM entrance
2	245	Avinashi	TMB24501	Entrance is at road level
3	245	Avinashi	TMB24502	Entrance is at road level
4	325	Pallagoundenpalayam	TMB32501	Entrance is at road level
5	325	Pallagoundenpalayam	TMB32502	Entrance is at road level
6	058	Podanur	TMB05802	Entrance is at road level
7	058	Podanur	TMB05803	Not enough space to provide Ramp Facility
8	058	Podanur	TMB05804	Entrance is at road level
9	179	Perundurai	TMB17901	Entrance is at a height with many steps
10	376	Saravanampatti	TMB37601	Entrance is at a height, with many steps
11	397	Gudalur	TMB39701	ATM Entrance is at road level. So, Not Required
12	326	Madampalayam	TMB32602	The ATM is very near to Highway and there is no space for ramp.
13	297	Dharapuram	TMB29702	Entrance is at road level
14	335	Madhvarayapuram	TMB33502	Entrance is at road level
15	232	Kavundampalayam	TMB23203	No space. ATM is very near to road.
16	232	Kavundampalayam	TMB23201	No space due to corporation drainage.
17	305	Coonoor	TMB30502	Entrance is at road level
18	305	Coonoor	TMB30503	Entrance is at road level
19	036	Erode	TMB03602	Entrance is at road level
20	036	Erode	TMB03603	Entrance is at road level
21	036	Erode	TMB03604	Entrance is at road level
22	036	Erode	TMB03605	Entrance is at road level
23	036	Erode	TMB03606	Entrance is at road level
24	203	Kunnathur	TMB20301	Entrance is at a height, with many steps
25	187	Bhavani	TMB18703	Entrance is at a height, with many steps
26	090	Pollachi	TMB09001	Entrance is at a height, with many steps
27	198	Perumanallur	TMB19803	Entrance is at road level
28	075	Tirupur	TMB07501	Entrance is at road level
29	075	Tirupur	TMB07502	Entrance is at road level
30	075	Tirupur	TMB07503	Entrance is at road level
31	075	Tirupur	TMB07504	No space
32	121	Dr.Nanjappa road	TMB12102	Entrance is at road level
33	121	Dr.Nanjappa road	TMB12104	Entrance is at road level
34	121	Dr.Nanjappa road	TMB12106	Entrance is at road level

35	121	Dr.Nanjappa road	TMB12105	Entrance is at a height, with many steps
36	121	Dr.Nanjappa road	TMB12107	Entrance is at road level
37	136	Coimbatore R.S.Puram	TMB13601	Entrance is at a height, with many steps
38	136	Coimbatore R.S.Puram	TMB13602	Entrance is at a height, with many steps
39	136	Coimbatore R.S.Puram	TMB13603	Entrance is at a height, with many steps
40	136	Coimbatore R.S.Puram	TMB13604	Entrance is at a height, with many steps
41	016	Coimbatore Main	TMB01605	Entrance is at a height, with many steps
42	179	Perundurai	TMB17903	Entrance is at road level
43	361	Kanakkankadu	TMB36102	Entrance is at road level
44	420	Singanallur	TMB42001	Entrance is at road level
45	136	Coimbatore R.S.Puram	TMB13605	Entrance is at a height, with many steps
46	245	Avinashi	TMB24503	Entrance is at road level
47	225	Annur	TMB22501	Entrance is at road level
48	225	Annur	TMB22502	No space
49	225	Annur	TMB22503	No space
50	374	Malayandipatnam	TMB37403	No sufficient space for construction of RAMP facility.

3. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp
		Nil		

Hyderabad Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	12
2	Total number of branches where construction of Ramps is not feasible (*)	25
3	Total number of branches where construction of Ramps is feasible	Nil

	(**)	
--	------	--

1. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	065	Hyderabad	Branch is in first floor
2.	074	Guntur	Branch is in first floor
3.	083	Kolkatta	Branch is in second floor
4.	107	Nellore	Entrance is at a height with many steps
5.	120	Rajahmundry	Entrance is at a height with many steps
6.	124	Tadepalligudam	Entrance is at road level
7.	148	Visakhapatnam	Entrance is at road level
8.	170	Tirupathi	Entrance is at road level
9.	172	Cuttack	Entrance is at road level
10.	190	Nandyal	Entrance is at a height with many steps
11.	266	Gollapudi	Entrance is at a height with many steps
12.	273	Chebrolu	Entrance is at road level
13.	284	Pedanandipadu	Entrance is at a height with many steps
14.	299	Tanuku	Entrance is at a height with many steps
15.	308	Vinukonda	Branch is functioning in first floor
16.	320	Jaggayyapet	Entrance is at a height with many steps
17.	330	Mandapeta	Entrance is at road level
18.	358	Miryalguda	Branch is functioning in first floor
19.	362	Chilakaluripet	Entrance is at road level
20.	373	Suryapet	Entrance is at a height with many steps
21.	386	Narasaraopet	Entrance is at a height with many steps
22.	387	Kavali	Entrance is at a height with many steps
23.	435	Srikalahasti	Branch in the first floor
24.	446	Bhimavaram	No sufficient space
25.	482	Raipur	Entrance is at road level

2. Progress in construction of Ramp at branches, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	The progress in construction of Ramp	Remarks
NIL				

Hyderabad Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	25
2	Total number of ATMs where construction of Ramps is not feasible (*)	36
3	Total number of ATMs where construction of Ramps is feasible (**)	Nil

2. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
1	065	Hyderabad	TMB06502	Entrance is at a height, with many steps
2	074	Guntur	TMB07401	Entrance is at road level
3	083	Kolkata	TMB08302	Entrance is at a height, with many steps
4	097	Vijayawada	TMB09702	Entrance is at a height, with many steps
5	107	Nellore	TMB10701	Entrance is at road level
6	107	Nellore	TMB10702	Entrance is at road level
7	120	Rajahmundry	TMB12002	Entrance is at road level
8	124	Tadepalligudem	TMB12401	Entrance is at road level
9	124	Tadepalligudem	TMB12402	Entrance is at road level
10	148	Visakhapatnam	TMB14802	Entrance is at road level
11	167	Kakinada	TMB16703	Entrance is at road level
12	170	Tirupathi	TMB17001	Entrance is at road level
13	170	Tirupathi	TMB17002	No space for providing ramp
14	170	Tirupathi	TMB17003	Entrance is at road level
15	172	Cuttack – Onsite	TMB17202	Entrance is at road level
16	190	Nandyal	TMB19001	Entrance is at a height, with many steps
17	190	Nandyal	TMB19002	Entrance is at a height, with many steps
18	213	Rikab Gunj	TMB21302	Entrance is at a height, with many steps
19	266	Gollapudi	TMB26601	Entrance is at a height, with many steps
20	266	Gollapudi	TMB26602	Steps at public path
21	273	Chebrolu	TMB27301	Entrance is at road level
22	284	Pedanandipadu	TMB28401	Entrance is at a height, with many steps
23	299	Tanuku	TMB29901	Entrance is at a height, with many steps
24	299	Tanuku	TMB29902	Entrance is at road level
25	320	Jaggayyapet	TMB32001	Entrance is at a height, with 4 steps
26	358	Miryalguda	TMB35801	ATM is in the first floor
27	362	Chilakaluripet	TMB36201	Entrance is at road level
28	373	Suryapet	TMB27301	Entrance is at a height, with many steps
29	386	Narasaraopet	TMB38601	Entrance is at a height, with many steps
30	074	Guntur	TMB07402	Entrance is at road level

31	074	Guntur	TMB07403	Entrance is at road level
32	120	Rajahmundry	TMB12003	Entrance is at road level
33	107	Nellore	TMB10703	Entrance is at road level
34	437	Srikalahasti	TMB43701	Entrance is small
35	482	Raipur	TMB48201	Entrance is at road level
36	170	Tirupathi	TMB17005	Entrance is at platform level

3. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp
		NIL		

Madurai Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	34
2	Total number of branches where construction of Ramps is not feasible (*)	26
3	Total number of branches where construction of Ramps is	Nil

	feasible (**)	
--	---------------	--

1. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	002	Madurai Main	Entrance at road level
2.	006	Dindigul	Entrance at road level
3.	070	Usilampatti	Entrance at height with huge steps
4.	089	Palani	Branch in first floor
5.	093	Simmakkal	Entrance at height with many steps
6.	118	Madurai Chinthamani	Entrance at height with few steps
7.	131	Ramanathapuram	Branch in first floor
8.	153	Thirumangalam	Branch in first floor
9.	155	Cumbum	Branch in first floor
10.	163	Madurai Tallakulam	Branch in first floor
11.	237	Melur	Entrance at road level
12.	257	Mudhukulathur	Entrance at road level
13.	262	Poovanthi	Branch in first floor
14.	271	Oddanchatram	Branch in first floor
15.	283	Chinnalapatti	Branch in first floor
16.	288	Uchipuli	Entrance at road level
17.	289	Checkanurani	Branch in first floor
18.	300	Sevagampatti	Branch in first floor
19.	327	Villapuram	Entrance at road level
20.	343	Iravathanallur	Entrance at height with many steps
21.	371	Rameswaram	Entrance at road level
22.	451	Madurai-K.K.Nagar	The branch is situated at 80 feet main road
23.	291	Devakottai	No space
24.	381	Madurai S.S.Colony	Entrance at road level
25.	220	Andipatti	No space
26.	497	Tirupattur	Temporary premises

2. Progress in construction of Ramp at branches, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	The progress in construction of Ramp
		Nil	

Madurai Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	61
2	Total number of ATMs where construction of Ramps is not feasible (*)	80
3	Total number of ATMs where construction of Ramps is feasible (**)	Nil

2. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
1	002	Madurai Main	TMB00201	Out of 6 offsite ATMs, Entrance is at road level for 5 offsite ATM's. For South Marret (00207) ATM there is only 2 steps to access for the customer. We have proposed to vacate the Vasanth Nagar Offsite ATM (00202) in which the entrance is at a height of more than 6 steps to access.
2	002	Madurai Main	TMB00203	
3	002	Madurai Main	TMB00204	
4	002	Madurai Main	TMB00205	
5	002	Madurai Main	TMB00206	
6	002	Madurai Main	TMB00207	
7	002	Madurai Main	TMB00208	
8	006	Dindigul	TMB00601	Entrance is at a height with two steps
9	006	Dindigul	TMB00602	
10	006	Dindigul	TMB00603	
11	051	Eriyodu	TMB05102	ATM is in road level.
12	070	Usilampatti	TMB07001	Entrance have 4 steps high
13	070	Usilampatti	TMB07002	
14	089	Palani	TMB08902	Entrance at road level
15	089	Palani	TMB08903	Entrance at road level
16	093	Mad-Simmakkal	TMB09303	There is no space to drive the tri-cycle inside the ATM premises.
17	093	Mad-Simmakkal	TMB09305	
18	093	Mad-Simmakkal	TMB09306	
19	093	Mad-Simmakkal	TMB09307	
20	093	Mad-Simmakkal	TMB09308	
21	115	Chockalingapuram	TMB11502	ATM at 5 feet above the road level
22	118	Mad-Chinthamani	TMB11801	Entrance height with few steps. ATM entrance is at ground level.
23	093	Mad- Simmakkal	TMB09311	
24	118	Mad-Chinthamani	TMB11804	
25	118	Mad-Chinthamani	TMB11805	
26	118	Mad-Chinthamani	TMB11806	
27	118	Mad-Chinthamani	TMB11807	
28	118	Mad-Chinthamani	TMB11808	
29	118	Mad-Chinthamani	TMB11809	
30	118	Mad-Chinthamani	TMB11810	
31	118	Mad-Chinthamani	TMB11811	
32	118	Mad-Chinthamani	TMB11812	
33	131	Ramanathapuram	TMB13102	
34	131	Ramanathapuram	TMB13103	Entrance at road level
35	131	Ramanathapuram	TMB13104	Entrance at road level
36	155	Cumbum	TMB15501	Entrance has many steps
37	155	Cumbum	TMB15503	

38	180	Bodinayakanur	TMB18002	ATM has many steps.
39	220	Andipatti	TMB22001	ATM entrance is in the road level.
40	237	Melur	TMB23701	Entrance is at road level
41	237	Melur	TMB23702	Entrance at road level
42	241	Natham	TMB24101	Entrance is at a height, with many steps.
43	241	Natham	TMB24102	Entrance is at a height, with many steps.
44	257	Mudhukulathur	TMB25701	Entrance is at road level
45	271	Oddanchatram	TMB27101	Only two stair cases with low platform.
46	288	Uchipuli	TMB28801	Entrance is at road level
47	289	Checkanurani	TMB28901	Entrance is at road level
48	300	Sevagampatti	TMB30002	Almost it is in ground level
49	327	Villapuram	TMB32702	Entrance is at road level.
50	343	Iravathanallur	TMB34301	Entrance is at height, with many steps
51	371	Rameswaram	TMB37101	Entrance is at road level
52	381	Madurai S.S.Colony	TMB38101	Entrance is small front area covered by Generator
53	163	Tallakulam	TMB16302	Entrance at road level
54	163	Tallakulam	TMB16303	Entrance at road level
55	163	Tallakulam	TMB16304	Entrance at road level
56	163	Tallakulam	TMB16305	Entrance at road level
57	163	Tallakulam	TMB16306	Entrance at road level
58	163	Tallakulam	TMB16307	Entrance at road level
59	305	Usilampatti	TMB30501	Entrance is at height, with 4 steps
60	305	Usilampatti	TMB30502	Entrance is at height, with 4 steps
61	181	Paramakudi	TMB18102	Entrance at road level
62	276	Thirunagar	TMB27602	Ground level
63	002	Madurai Main	TMB00209	No space
64	002	Madurai Main	TMB00210	No space
65	048	Chinnamanur	TMB04802	Entrance is at height, with many steps
66	093	Madurai Simmakkal	TMB09309	No space
67	181	Paramakudi	TMB18103	With one step only. It is pathway in a complex
68	451	Madurai-K.K.Nagar	TMB45101	The branch is situated at 80 feet main road
69	072	Pannaipuram	TMB07202	Entrance at road level
70	291	Devakottai	TMB29101	No space
71	007	Theni	TMB00702	Not feasible
72	007	Theni	TMB00703	Not feasible
73	127	Karaikudi	TMB12702	It is located in complex area.

74	276	Thirunagar	TMB27601	Not feasible
75	283	Chinnalapatti	TMB28301	Not feasible
76	237	Melur	TMB23703	Not feasible
77	163	Tallakulam	TMB16308	Ground level
78	089	Palani	TMB08901	No space
79	508	Madurai_Palanganat ham	TMB50801	Entrance is at height, with many steps
80	271	Oddanchatram	TMB27102	Ground level

3. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp
		Nil		

Mumbai Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	10
2	Total number of branches where construction of Ramps is not feasible (*)	25
3	Total number of branches where construction of Ramps is feasible (**)	Nil

1. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	066	Mumbai Mandvi	Entrance is at a height, with many steps
2.	100	Delhi	Branch is in first floor
3.	143	Ichalkaranchi	Entrance is at a height, with many steps

4.	151	Pune	Entrance is at road level
5.	162	Mumbai Andheri (E)	Entrance is at road level
6.	168	Mumbai Sion	Entrance is at road level
7.	207	Sahadara – Delhi	Entrance is at road level
8.	211	Ghaziabad	Entrance is at a height, with many steps
9.	214	Andheri (W) Mumbai	Entrance is at road level
10.	217	Sewri – Mumbai	Entrance is at road level
11.	218	Chembur – Mumbai	Entrance is at road level
12.	219	Karolbagh – Delhi	Branch in first floor
13.	233	Mumbai Dharavi	Entrance is at a height, with many steps
14.	256	Boisar	Entrance is at road level
15.	293	Sukapur	Entrance is at road level
16.	294	Vita	Branch is in first floor
17.	296	Madhavnagar	Branch is in first floor
18.	314	Ratnagiri	Branch is in first floor
19.	315	Jaysingpur	Branch is in first floor
20.	322	Pithampur	Branch is in upper first floor
21.	334	Nanded	Entrance is at a height, with many steps
22.	421	Manmad	Entrance is at a height, with many steps
23.	432	Chiplun	Entrance is at road level
24.	117	Mumbai Vashi	Entrance is at road level
25.	458	Faridabad	Upper ground floor

2. Progress in construction of Ramp at branches, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	The progress in construction of Ramp
		Nil	

Mumbai Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	16
2	Total number of ATMs where construction of Ramps is not feasible (*)	27
3	Total number of ATMs where construction of Ramps is feasible (**)	Nil

2. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
--------	------------	--------------------	--------	---

1	219	Karolbagh	TMB21901	Entrance is at a height, with many steps
2	217	Sewri	TMB21701	Entrance is at road level
3	256	Boisar	TMB25601	Entrance is at road level
4	314	Ratnagiri	TMB31402	Drainage Platform has been constructed between Road and ATM
5	293	Sukapur	TMB29301	Entrance is at road level
6	211	Ghaziabad	TMB21101	Entrance is at a height, with many steps
7	218	Chembur	TMB21801	ATM is inside the branch building premises
8	168	Sion	TMB16801	Entrance is at road level
9	315	Jaysingpur	TMB31501	Entrance is at road level
10	151	Pune	TMB15101	Entrance is at road level
11	117	Vashi	TMB11702	Entrance is at a height, with many steps
12	162	Andheri East	TMB16201	Entrance is at road level
13	334	Nanded	TMB33401	Entrance is at a height, with many steps
14	233	Dharavi	TMB23301	Entrance is at a height, with many steps
15	233	Dharavi	TMB23302	Entrance is at a height, with many steps
16	207	Shahdara	TMB20701	Entrance is at road level
17	143	Ichalkaranji	TMB14301	Entrance is at a height, with many steps
18	322	Pithampur	TMB32201	ATM is in upper ground floor
19	151	Pune	TMB15103	Entrance is at road level
20	256	Boisar	TMB25602	Entrance is at road level
21	214	Andheri west	TMB21401	Entrance is at road level
22	334	Nanded	TMB33401	Upper ground floor
23	223	Silvassa	TMB22303	Entrance is at road level
24	458	Faridabad	TMB45801	Situated at Upper ground floor
25	421	Manmad	TMB42101	Not Feasible
26	117	Vashi	TMB11701	Not Feasible
27	484	Mumbai-Mulund	TMB48401	ATM is inside of branch

3. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp
		Nil		

Thoothukudi Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	34
2	Total number of branches where construction of Ramps is not feasible (*)	25
3	Total number of branches where construction of Ramps is feasible (**)	Nil

1. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl. No	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	003	Sivakasi	Entrance at a height, with many steps
2.	013	Puthiamputhur	Entrance gate to be reconstructed to large extent
3.	021	Kommadikottai	Width of entrance is very small.

4.	027	Mullakadu	Old Premises
5.	033	Elayirampennai	Branch is in first floor
6.	034	Kovilpatti	Branch is in first floor
7.	038	Aruppukottai	Entrance at road level
8.	039	Kalloorani	Entrance at road level
9.	053	Siruthondanallur	Entrance at road level
10.	054	Prahasapuram	Entrance at road level
11.	111	Pandaravilai	Not necessary
12.	156	Sipcot, Thoothukudi	Branch is in first floor
13.	194	Sivakasi, A.J.College	Entrance at a height, with many steps
14.	252	Author	Entrance at road level
15.	255	Udangudi	Entrance at road level
16.	274	Kariapatti	Branch is in first floor
17.	275	Kulathur	Entrance at road level
18.	304	Soolakarai	One and half feet above the road level
19.	319	Pasuvanthanai	Branch is in first floor
20.	328	Srivilliputhur	Entrance at road level
21.	352	Kulayankarisal	Entrance at road level
22.	369	Allampatti	Entrance at a height, with many steps
23.	377	Thoothukudi Port Trust	Entrance at a height, with many steps
24.	449	Nalumavadi	Temporary premises
25.	456	Erichanatham	First Floor, Temporary premises

2. Progress in construction of Ramp at branches, where it is feasible:

Sl.No	Branch No.	Name of the Branch	The progress in construction of Ramp
		Nil	

Thoothukudi Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	85
2	Total number of ATMs where construction of Ramps is not feasible (*)	82
3	Total number of ATMs where construction of Ramps is feasible (**)	Nil

2. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
1	369	Allampatti	TMB36901	Entrance is at Road level
2	038	Aruppukottai	TMB03801	
3	038	Aruppukottai	TMB03808	
4	252	Author	TMB25202	
5	252	Author	TMB25203	

6	252	Author	TMB25204		
7	236	Chatrapatti	TMB23601		
8	033	Elayirampennai	TMB03301		
9	039	Kalloorani	TMB03901		
10	274	Kariapatti	TMB27402		
11	352	Kulayankarisal	TMB35201		
12	352	Kulayankarisal	TMB35202		
13	054	Prahasapuram	TMB05402		
14	054	Prahasapuram	TMB05403		
15	240	Sankaraperi	TMB24003		
16	073	Rajapalayam	TMB07302		
17	231	Thiruthangal	TMB23101		
18	231	Thiruthangal	TMB23102		
19	231	Thiruthangal	TMB23103		
20	106	Thoothukudi South	TMB10602		
21	106	Thoothukudi South	TMB10603		
22	106	Thoothukudi South	TMB10606		
23	001	Thoothukudi Main	TMB00102		
24	001	Thoothukudi Main	TMB00103		
25	001	Thoothukudi Main	TMB00104		
26	001	Thoothukudi Main	TMB00107		
27	001	Thoothukudi Main	TMB00108		
28	001	Thoothukudi Main	TMB00109		Entrance is at Road level
29	004	Virudhunagar	TMB00403		
30	004	Virudhunagar	TMB00406		
31	010	Muhavoor	TMB01001		
32	156	Sipcot	TMB15602		
33	156	Sipcot	TMB15603		
34	156	Sipcot	TMB15604		
35	194	AJ College	TMB19401		
36	194	AJ College	TMB19402		
37	243	Sathankulam	TMB24301		
38	243	Sathankulam	TMB24302		
39	328	Srivilliputhur	TMB32801		
40	328	Srivilliputhur	TMB32802		
41	022	Megnanapuram	TMB02201		
42	003	Sivakasi	TMB00301		
43	003	Sivakasi	TMB00303		
44	003	Sivakasi	TMB00305		
45	053	Siruthondanallur	TMB05301		
46	053	Siruthondanallur	TMB05302		
47	038	Aruppukottai	TMB03805	Entrance at height with many steps	
48	349	Kannicheriputhur	TMB34901		
49	021	Kommadikottai	TMB02102		
50	034	Kovilpatti	TMB03401		
51	111	Pandaravillai	TMB11102		
52	319	Pasuvanthanai	TMB31901		

53	377	Port Trust	TMB37701	
54	240	Sankaraperi	TMB24001	
55	240	Sankaraperi	TMB24002	
56	073	Rajapalayam	TMB07303	
57	434	Mattakadai	TMB43401	
58	009	Vilathikulam	TMB00902	
59	003	Sivakasi	TMB00302	
60	003	Sivakasi	TMB00304	
61	003	Sivakasi	TMB00306	
62	275	Kulathur	TMB27501	There is no enough space to construct Ramp as the step is the starting point of the site
63	027	Mullakkadu	TMB02701	Old Premises
64	027	Mullakkadu	TMB02702	Old Premises
65	027	Mullakkadu	TMB02703	Not feasible
66	111	Pandaravilai	TMB11101	Not feasible
67	017	Pudur	TMB01702	Only one step from road level of off site atm
68	073	Rajapalayam	TMB07304	There is long ditch between road and atm entrance level
69	156	Sipcot	TMB15601	ATM is at upper ground floor
70	003	Sivakasi	TMB00307	Entrance at height with many steps
71	255	Udangudi	TMB25502	Entrance is at road level
72	369	Allampatti	TMB36903	No space
73	003	Sivakasi	TMB00308	No steps – Ground level
74	034	Kovilpatti	TMB03402	Not Feasible
75	034	Kovilpatti	TMB03403	Not Feasible
76	004	Virudhunagar	TMB00409	No space
77	038	Arupukottai	TMB03804	Ground level, Not feasible
78	024	Kayamozhi	TMB02402	Ground level
79	34	Kovilpatti	TMB03406	No space, very close to road
80	003	Sivakasi	TMB00310	Entrance at height with many steps
81	003	Sivakasi	TMB00311	Entrance at height with many steps
82	106	Thoothukudi South	TMB10609	Entrance at height with many steps

3. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp
		Nil		-

Tiruchirapalli Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	22
2	Total number of branches where construction of Ramps is not feasible (*)	14
3	Total number of branches where construction of Ramps is feasible (**)	Nil

1. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	019	Tiruchirapalli	Branch in first floor
2.	043	Thiruvarur	Entrance is at road level
3.	084	Cuddalore	Entrance is at road level
4.	087	Karur	Branch in first floor
5.	128	Pudukottai	Branch is in first floor
6.	182	Virudhachalam	Branch in first floor

7.	184	Aranthangi	Entrance at road level
8.	195	Panruti	Entrance at a height with many steps
9.	249	Ariyalur	Branch is in first floor
10.	281	Perambalur	Branch is in first floor
11.	312	Chidambaram	Branch is in first floor
12.	379	Thillainagar	Entrance at a height with many steps
13.	466	Kurinjpadi	Branch in the first floor
14.	510	Trichy_Srinivasanagar	Branch in the first floor

2. Progress in construction of Ramp at branches, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	The progress in construction of Ramp
		Nil	

Tiruchirapalli Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	60
2	Total number of ATMs where construction of Ramps is not feasible (*)	39
3	Total number of ATMs where construction of Ramps is feasible (**)	Nil

2. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
1	019	Tiruchirapalli	TMB01903	Not feasible
2	019	Tiruchirapalli	TMB01901	Entrance is at road level
3	019	Tiruchirapalli	TMB01907	Entrance is at road level
4	019	Tiruchirapalli	TMB01908	Entrance is at road level
5	043	Thiruvarur	TMB04301	Entrance is at road level
6	067	Thanjavur	TMB06702	Entrance is at road level
7	084	Cuddalore	TMB08401	Entrance is at road level

8	084	Cuddalore	TMB08402	Entrance is at road level
9	084	Cuddalore	TMB08403	Entrance is at road level
10	087	Karur	TMB08703	Entrance is at road level
11	087	Karur	TMB08704	Entrance is at road level
12	094	Mayiladuthurai	TMB09402	Entrance is at road level
13	128	Pudukottai	TMB12801	ATM is in first floor
14	128	Pudukottai	TMB12802	Entrance is at a height with many steps
15	128	Pudukottai	TMB12803	Entrance is at road level
16	182	Virudhachalam	TMB18201	ATM is in first floor
17	182	Virudhachalam	TMB18202	Entrance is at road level
18	184	Aranthangi	TMB18401	Entrance is at road level
19	195	Panruti	TMB19501	Entrance is at a height with many steps
20	195	Panruti	TMB19503	Entrance is at road level
21	249	Ariyalur	TMB24902	Entrance is at road level
22	281	Perambalur	TMB28101	Entrance is at a height with many steps
23	281	Perambalur	TMB28102	Entrance is at road level
24	290	Bikshandar koil	TMB29004	Entrance is at road level
25	312	Chidambaram	TMB31203	Entrance is at road level
26	356	Vazhkkai	TMB35602	Entrance is at road level
27	379	Thillai Nagar	TMB37901	Entrance is at a height with many steps
28	242	Thuraiyur	TMB24202	Entrance is at road level
29	398	Ayyampalayam	TMB39801	Entrance is at road level
30	182	Virudhachalam	TMB18203	ATM is in first floor
31	184	Aranthangi (Onsite Addl.)	TMB18402	Entrance is at Road level
32	128	Pudukottai (Addl.)04	TMB12804	Entrance is at a height with many steps
33	466	Kurinjipadi	TMB46601	Entrance is at Road level
34	019	Tiruchirapalli	TMB01905	Not Feasible
35	043	Thiruvarur	TMB04302	Not Feasible
36	307	Pattukottai	TMB30702	Entrance is at road level
37	307	Pattukottai	TMB30703	E-Lobby is in first floor
38	184	Aranthangi	TMB18404	ATM Located inside the shopping complex area
39	312	Chidambaram	TMB31205	Entrance is at road level

3. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp
		Nil		

Tirunelveli Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	22
2	Total number of branches where construction of Ramps is not feasible (*)	16
3	Total number of branches where construction of Ramps is feasible (**)	Nil

1. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	040	Alangulam	No Space
2.	139	Sankarankoil	Road level
3.	159	Valliyoor	First floor
4.	176	Vadakkankulam	Road level
5.	197	Shenkottai	Road level
6.	230	Pettai Rural	No Space
7.	248	Panagudi	First Floor
8.	250	Punnaiyapuram	No Space
9.	261	Kuthukalvalasai	First Floor
10.	279	Kalakad	First Floor
11.	318	Kadayanallur	No Space
12.	340	Venkateswarapuram	Entrance at height
13.	344	Thippanampatti	Entrance at height
14.	409	Vickramasingapuram	Not Feasible
15.	502	Tirunelveli Vannarapettai	First Floor
16.	030	Tisayanvilai	Ground level

2. Progress in construction of Ramp at branches, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	The progress in construction of Ramp	Remarks
		Nil		

Tirunelveli Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	57
2	Total number of ATMs where construction of Ramps is not feasible (*)	71
3	Total number of ATMs where construction of Ramps is feasible (**)	Nil

1. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl. No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
1	279	Kalakkad	TMB27903	Entrance is at road level
2	340	Venkateswarapuram	TMB34002	Entrance is at road level
3	279	Kalakkad	TMB27901	Entrance is at road level
4	279	Kalakkad	TMB27902	Entrance is at road level
5	230	Pettai rural	TMB23005	Entrance is at road level
6	318	Kadayanallur	TMB31802	Entrance is at road level
7	197	Shenkottai	TMB19702	Entrance is at road level
8	159	Valliyoor	TMB15902	Entrance is at road level
9	250	Punnaiyapuram	TMB25001	Entrance is at road level
10	261	Kuthukalvalasai	TMB26102	Entrance is at road level
11	086	Venkadampatti	TMB08602	Entrance is at road level
12	339	Pappakudi	TMB33902	Entrance is at road level
13	279	Kalakkad	TMB27904	Entrance is at road level
14	230	Pettai rural	TMB23003	Entrance is at road level
15	025	Tirunelveli	TMB02502	Entrance is at road level
16	230	Pettai rural	TMB23004	Entrance is at road level
17	012	Pavoorchatram	TMB01201	Entrance is at road level
18	029	Radhapuram	TMB02901	Entrance is at road level
19	029	Radhapuram	TMB02902	Entrance is at road level
20	012	Pavoorchatram	TMB01204	Entrance is at road level
21	139	Sankarankoil	TMB13901	Entrance is at road level
22	230	Pettai rural	TMB23002	Entrance is at road level
23	031	T.Kallikulam	TMB03102	Entrance is at road level
24	139	Sankarankoil	TMB13902	Entrance is at road level
25	025	Tirunelveli	TMB02503	Entrance is at road level
26	344	Thippanampatti	TMB34401	Entrance is at a height, with many steps
27	344	Thippanampatti	TMB34402	Entrance is at a height, with many steps
28	040	Alangulam	TMB04006	Entrance is at a height, with many steps
29	338	Reddiarpatti	TMB33802	Entrance is at a height, with many steps
30	318	Kadayanallur	TMB31801	Entrance is at a height, with many steps
31	30	Tisaiyanvilai	TMB03003	Entrance is at a height, with many steps
32	197	Shenkottai	TMB19705	Entrance is at a height, with many steps
33	409	Vickramasingapuram	TMB40901	Entrance is at a height, with many steps

34	340	Venkateswarapuram	TMB34001	Entrance is at a height, with many steps
35	012	Pavoorchatram	TMB01202	Entrance is at a height, with many steps
36	365	Servaikaranpatti	TMB36502	Entrance is at a height, with many steps
37	176	Vadakkankulam	TMB17602	Entrance is at a height, with many steps
38	197	Shenkottai	TMB19703	Entrance is at a height, with many steps
39	339	Pappakudi	TMB33903	Entrance is at a height, with many steps
40	040	Alangulam	TMB04004	Entrance is at a height, with many steps
41	197	Shenkottai	TMB19701	Entrance is at a height, with many steps
42	030	Tisaiyanvilai	TMB03004	Entrance is at a height, with many steps
43	040	Alangulam	TMB04002	Entrance is at a height, with many steps
44	176	Vadakkankulam	TMB17603	Entrance is at a height, with many steps
45	040	Alangulam	TMB04003	Entrance is at a height, with many steps
46	176	Vadakkankulam	TMB17605	Entrance is at a height, with many steps
47	012	Pavoorchatram	TMB01205	Entrance is at a height, with many steps
48	012	Pavoorchatram	TMB01203	Entrance is at a height, with many steps
49	197	Shenkottai	TMB19704	Entrance is at a height, with many steps
50	029	Radhapuram	TMB02903	Entrance is at a height, with many steps
51	248	Panagudi	TMB24801	Entrance is at a height, with many steps
52	176	Vadakkankulam	TMB17601	Entrance is at a height, with many steps
53	025	Tirunelveli	TMB02505	Entrance is at a height, with many steps
54	355	Kuruvikulam	TMB35502	Entrance is at a height, with many steps
55	176	Vadakkankulam	TMB17608	Entrance is at a height, with many steps
56	176	Vadakkankulam	TMB17607	Entrance is at a height, with many steps
57	176	Vadakkankulam	TMB17606	Entrance is at a height, with many steps
58	261	Kuthukalvalasai	TMB26101	Entrance is at a height, with many steps
59	176	Vadakkankulam	TMB17604	Entrance is at a height, with many steps
60	025	Tirunelveli	TMB02504	Entrance is at a height, with many steps
61	250	Punnaiyapuram	TMB25003	Entrance is at a height, with many steps
62	365	Servaikaranpatti	TMB36503	Entrance is at a height, with many steps
63	250	Punnaiyapuram	TMB25002	Entrance is at a height, with many steps
64	250	Punnaiyapuram	TMB25005	Entrance is at road level
65	159	Valliyoor	TMB15903	Entrance in 8 feet height
66	025	Tirunelveli	TMB02507	Floor level – only 4 inch height
67	031	T.Kallikulam	TMB03104	0.75 ft height only from the road
68	248	Panagudi	TMB24804	It is nearby to the road
69	324	Thiruvengadam	TMB32401	Not feasible
70	324	Thiruvengadam	TMB32403	The ATM building is located on the main road and the total width of the entrance is only 4 ft.
71	025	Tirunelveli	TMB02507	Entrance is at road level

2. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp
		Nil		

Thiruvananthapuram Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	24
2	Total number of branches where construction of Ramps is not feasible (*)	22
3	Total number of branches where construction of Ramps is feasible (**)	Nil

1. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	042	Thickanamcode	Branch in first floor
2.	046	Palliyadi	Entrance at Road level
3.	047	Verkhizambi	Entrance at Road level
4.	050	Agasteeswaram	Entrance at Road level
5.	064	Thiruvananthapuram	Branch in first floor
6.	092	Edalakudy	Entrance at Road level
7.	095	Kollam	Branch in first floor
8.	112	Ernakulam	Entrance at Road level
9.	122	Kozhikode	Branch in first floor
10.	149	Kottayam	Branch in first floor
11.	177	Algappapuram	Entrance at Road level
12.	183	Pillayarapuram	Entrance at Road level
13.	269	Therekalputhur	Branch in first floor
14.	380	Pappanamcode	Branch in first floor
15.	383	Pathanamthitta	Branch in first floor
16.	412	Kayankulam	Entrance at Road level
17.	414	Kanhangad	Branch in first floor
18.	470	Malappuram	Branch in first floor
19.	474	Payyanur	Branch in first floor
20.	476	Kasaragod	Branch in first floor
21.	477	Kodungallur	Branch in first floor
22.	485	Taliparamba	Branch in upper Ground Floor

2. Progress in construction of Ramp at branches, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	The progress in construction of Ramp	Remarks
			NIL	

Thiruvananthapuram Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	56
2	Total number of ATMs where construction of Ramps is not feasible (*)	24
3	Total number of ATMs where construction of Ramps is feasible (**)	Nil

2. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
1	069	Arumanai	TMB06903	Entrance is at a height, with many steps
2	095	Kollam	TMB09501	
3	095	Kollam	TMB09502	
4	270	Kanyakulam	TMB27003	
5	064	Thiruvananthapura	TMB06401	
6	270	m	TMB27001	
7	316	Kanyakulam	TMB31601	
8	026	Aralvaimozhi	TMB02602	
9	042	Thalakkulam	TMB04201	
10	042	Thickanamcode	TMB04202	
11	380	Karungal	TMB38001	
12	177	Pappanamcode	TMB17702	
13	050	Azhagappapuram	TMB05002	
14	069	Agasteeswaram Arumanai	TMB06902	
15	046	Palliyadi	TMB04601	Entrance is at road level
16	183	Pillayarpuram	TMB18302	Entrance is at road level
17	018	Anjugramam	TMB01803	More steps
18	122	Kozhikode	TMB12202	Entrance is at road level
19	177	Alagappapuram	TMB17703	Entrance is at road level
20	183	Pillayarpuram	TMB18303	No space
21	382	Karungal	TMB38202	No space
22	014	Rajakkamangalam	TMB01402	No space
23	470	Malappuram	TMB47001	No space
24	112	Ernakulam	TMB11202	The ATM is immediate to the road

3. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp
		Nil		

Salem Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	6
2	Total number of branches where construction of Ramps is not feasible (*)	33
3	Total number of branches where construction of Ramps is feasible (**)	Nil

1. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	23	Yercaud	Entrance is at a height with many steps
2.	28	Salem	Entrance is at road level
3.	41	Bommididi	Entrance is at road level
4.	45	Villupuram	Branch Entrance is very closed as First Floor steps
5.	60	Kannankurichi	Entrance is at road level
6.	80	Pavithrampudur	Entrance is at road level
7.	81	Pottireddipatti	Entrance is at road level
8.	126	Tiruchengodu	Entrance is at a height with many steps
9.	129	Namakkal	Entrance at height with many steps
10.	134	Thiruvannamalai	Entrance is at a height, with many steps
11.	138	Dharmapuri	Entrance is at road level
12.	173	Gingee	Entrance at height with many steps
13.	189	Tindivanam	Entrance at road level
14.	199	Rasipuram	Entrance at a height with many steps
15.	226	Vandavasi	Entrance is at a height, with many steps
16.	238	Chengam	Entrance is at road level
17.	244	Sankari	Located at elevated ground floor with several steps
18.	247	Elampillai	Entrance is at road level
19.	265	Koolipatti	Not feasible
20.	272	Kallakurichi	Entrance at road level
21.	285	Pallipalayam	Entrance is at road level
22.	286	Dasanaickenpatti	Entrance is at a height with many steps
23.	287	Pachanampatti	Entrance is at road level
24.	292	Tharamangalam	Entrance is at road level
25.	298	Harur	Entrance is at a height, with many steps
26.	303	Chinnappampatti	Entrance is at road level
27.	309	Arni	Entrance is at road level
28.	317	Attur	Space is very small to provide.
29.	321	Komarapalayam	Entrance is at road level
30.	331	Kalangani	Entrance is at road level

31.	345	Edappadi	Entrance is at a height with many steps
32.	363	Mettur	Branch is at first floor
33.	453	Salem_Ramakrishna Road	Branch is in First floor

2. Progress in construction of Ramp at branches, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	The progress in construction of Ramp	Remarks
		NIL		

Salem Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	20

2	Total number of ATMs where construction of Ramps is not feasible (*)	67
3	Total number of ATMs where construction of Ramps is feasible (**)	Nil

2. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
1	23	Yercaud	TMB02302	Entrance is at a height, with many steps
2	28	Salem	TMB02802	Entrance is at a height, with many steps
3	28	Salem	TMB02801	Entrance is at road level
4	28	Salem	TMB02803	Entrance is at road level
5	28	Salem	TMB02804	Entrance is at road level
6	41	Bommidi	TMB04101	Entrance is at road level
7	41	Bommidi	TMB04102	Entrance is at road level
8	41	Bommidi	TMB04103	No space
9	45	Villupuram	TMB04502	Entrance is at road level
10	45	Villupuram	TMB04501	Entrance is at road level
11	60	Kannankurichi	TMB06001	Entrance is at road level
12	60	Kannankurichi	TMB06002	Entrance is at road level
13	60	Kannankurichi	TMB06003	Entrance is at road level
14	80	Pavithramputhur	TMB08002	Entrance is at road level
15	80	Pavithramputhur	TMB08001	Entrance is at road level
16	81	Pottireddipatti	TMB08104	Entrance is at road level
17	126	Tiruchengode	TMB12602	Entrance is at a height with many steps
18	126	Tiruchengode	TMB12601	Entrance is at road level
19	129	Namakkal	TMB12902	Entrance is at road level
20	129	Namakkal	TMB12901	Entrance is at a height with many steps
21	129	Namakkal	TMB12903	Entrance is at road level
22	129	Namakkal	TMB12904	Entrance is at road level
23	134	Thiruvannamalai	TMB13401	Entrance is at a height, with many steps
24	134	Thiruvannamalai	TMB13402	Entrance is at road level
25	134	Thiruvannamalai	TMB13403	Entrance is at road level, Inadequate space
26	138	Dharmapuri	TMB13801	Entrance is at road level
27	138	Dharmapuri	TMB13802	Entrance is at road level
28	138	Dharmapuri	TMB13803	Entrance is at road level
29	138	Dharmapuri	TMB13805	Entrance is at road level
30	173	Gingee	TMB17301	Entrance is at a height, with many steps

31	189	Tindivanam	TMB18901	Entrance is at road level
32	199	Rasipuram	TMB19901	Entrance is at a height with many steps
33	199	Rasipuram	TMB19902	Entrance is at road level
34	226	Vandavasi	TMB22601	Entrance is at a height with many steps
35	226	Vandavasi	TMB22602	Entrance is at road level
36	226	Vandavasi	TMB22603	Entrance is at road level
37	238	Chengam	TMB23801	Entrance is at road level
38	238	Chengam	TMB23802	Entrance is at road level
39	244	Sankari	TMB24401	Entrance is at a height, with 10 steps
40	244	Sankari	TMB24402	Entrance is at road level
41	244	Sankari	TMB24403	Entrance is at road level
42	244	Sankari	TMB24404	Entrance is at height with many steps
43	244	Sankari	TMB24405	Entrance is at height with many steps
44	244	Sankari	TMB24407	Entrance is at road level
45	247	Elampillai	TMB24701	Entrance is at road level
46	264	Veppadai	TMB26402	Entrance is at road level
47	265	Koolipatti	TMB26501	Not feasible
48	272	Kallakurichi	TMB27201	Entrance is at road level
49	285	Pallipalayam	TMB28501	Entrance is at road level
50	285	Pallipalayam	TMB28502	Entrance is at road level
51	286	Dasanaickenpatti	TMB28601	Entrance is at road level
52	287	Pachanampatti	TMB28701	Not feasible
53	287	Pachanampatti	TMB28702	Entrance is at road level
54	292	Tharamangalam	TMB29201	Entrance is at road level
55	292	Tharamangalam	TMB29202	Entrance is at road level
56	298	Harur	TMB29801	Entrance is at a height, with many steps
57	303	Chinnappampatti	TMB30301	Entrance is at road level
58	303	Chinnappampatti	TMB30302	Entrance is at road level
59	309	Arni	TMB30901	Entrance is at road level
60	309	Arni	TMB30902	Entrance is at road level
61	321	Komarapalayam	TMB32101	Entrance is at road level
62	321	Komarapalayam	TMB32102	ATM is situated more than 4 ft from the earth level
63	331	Kalangani	TMB33101	Entrance is at road level
64	345	Edappadi	TMB34501	Entrance is at a height, with many steps
65	345	Edappadi	TMB34502	ATM is located 3ft height from road
66	363	Mettur	TMB36301	Entrance is at road level
67	363	Mettur	TMB36302	Not feasible

3. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp
1		Nil		

Ahmedabad Region

Branch Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of branches where Ramps are constructed	11
2	Total number of branches where construction of Ramps is not	13

	feasible (*)	
3	Total number of branches where construction of Ramps is feasible (**)	Nil

1. Reason for non-provision of Ramp at branches, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	Construction of Ramps is not feasible because
1.	113	Ahmedabad	Branch is in first floor
2.	119	Surat	Entrance is at road level
3.	130	Unjha	Entrance is at road level
4.	186	Bhilwara	Branch is in first floor
5.	253	Bhiwadi	Entrance is at a height, with many steps
6.	332	Sidhpur	Branch is in first floor
7.	348	Bardoli	Entrance is at road level
8.	390	Himatnagar	Entrance is at road level
9.	411	Deesa	Entrance is at road level
10.	461	Bilimora	No space, Very close to road
11.	475	Jaipur	Branch is in first floor
12.	480	Gondal	Entrance is at road level
13.	391	Vapi	Entrance is at road level

2. Progress in construction of Ramp at branches, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	The progress in construction of Ramp	Remarks
			Nil	

Ahmedabad Region

B. ATM Premises:

Sl.No.	As on 31.03.2022	Data
1	Total number of ATMs where Ramps are constructed	12

2	Total number of ATMs where construction of Ramps is not feasible (*)	14
3	Total number of ATMs where construction of Ramps is feasible (**)	Nil

2. Reason for non-provision of Ramp at ATMs, where it is not feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	Construction of Ramps is not feasible because
1	113	Ahmedabad	TMB11302	Entrance is at a height, with many steps
2	119	Surat	TMB11902	Entrance is at road level
3	130	Unjha	TMB13001	Entrance is at road level
4	150	vadodara	TMB15001	Entrance is at a height, with many steps
5	253	Bhiwadi	TMB25301	Entrance is at a height, with many steps
6	332	Sidhpur	TMB33201	Entrance is at road level
7	332	Sidhpur	TMB33202	The road is not wide and the ATM is very near to the road side
8	348	Bardoli	TMB34801	Entrance is at road level
9	390	Himatnagar	TMB39001	Entrance is at road level
10	391	Vapi	TMB39101	Entrance is at road level
11	411	Deesa	TMB41101	Entrance is at road level
12	461	Bilimora	TMB46101	No space, Very close to road
13	480	Gondal	TMB48001	Entrance is at road level
14	472	Rajkot	TMB47201	Not Feasible

3. Reason for non-provision of Ramp at ATMs, where it is feasible:

Sl.No.	Branch No.	Name of the Branch	ATM ID	The progress in construction of Ramp
		Nil		

Number of new branches opened after 01.01.2015	106 Nos.
Of which number of branches where ramp is “provided”	67 Nos.
Of which number of branches where ramp is “not feasible”	39 Nos.
Of which number of branches where ramp is “feasible”	Nil
Number of new ATMs opened after 01.01.2015	383 Nos.
Of which number of ATMs where ramp is “provided”	279 Nos.
Of which number of ATMs where ramp is “not feasible”	104 Nos.

Of which number of ATMs where ramp is “feasible”	Nil
--	-----

	RAMP details upto 31.03.2022					
	Branch	ATM				
	Constructed	Not feasible	Feasible (*)	Constructed	Not feasible	Feasible (*)
Bengaluru	10	23	0	23	42	0
Chennai	22	33	0	52	107	0
Coimbatore	30	18	0	68	50	0
Hyderabad	12	25	0	25	36	0
Madurai	34	26	0	61	80	0
Mumbai	10	25	0	16	27	0
Thoothukudi	34	25	0	85	82	0
Tiruchirapalli	21	14	0	60	39	0
Tirunelveli	22	16	0	57	71	0
Thiruvananthapuram	24	22	0	56	24	0
Salem	6	33	0	20	67	0
Ahmedabad	11	13	0	12	14	0
Total	236	273	0	528	636	0

(*) Regularly we are following the branches / Region to construct ramp at branch / ATM, wherever ramp construction is feasible.